

| PLATFORM ANNA | |
|--|---|
| Field Name: | Granite Point Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Amoco |
| Structural Design firm: | Earl & Wright/McDermott |
| Fabrication yard (structure): | Kaiser Steel in Oakland, California |
| Installation year and contractor: | 1965; McDermott |
| Water depth (at MLLW): | 77 feet |
| Number and diameter of legs: | Four legs; 14 feet diameter |
| Number, size and penetration of piling: | Eight piles per leg; 30 inch diameter; 87 feet penetration |
| Number, size and penetration of inner piling: | None |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | 137 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 8 wells Leg 2: 8 wells Leg 3: 7 wells Leg 4: 7 wells |
| Top girders storage tank liquid & capacity: | Crude Oil (A-T-0160, A-T-0170): 105,000 gal Power Oil (A-T-0220): 96,600 gal Produced Water (A-T-0310, A-T-0320): 25,200 gal Diesel Storage (A-T-0850): 105,000 gal Potable Water (A-T-3070): 50,4000 gal |
| Design criteria | |
| Ice thickness and strength: | Front legs 120 kips/ft. of diameter, back legs 50 kips/ft. |
| Wave height and period: | 30 feet with 9 second period |
| Wind: | 80 mph above elevation 25 feet |
| Earthquake: | 0.1 seismic ground motion |
| Current: | 3900 kips per leg impact load, seismic, ice and current loads applied simultaneously |
| Other Considerations: | Shadow effect |
| Unusual circumstances during installation: | None |

| | |
|---|---|
| Significant modification or damage to topsides: | Minor module additions. Damaged structural members requiring engineering evaluation, moderate general/local corrosion, extreme general corrosion on electrical connections and boxes, unsecured drums, valves, racks, chemical totes, ladders, piping and dunnage. Last inspected: 3/13 |
| Significant structural damage incidents: | Crack in top portion of weld connecting the west end of the center horizontal to the west horizontal (spans 7" and total length of 10"). Inspected in 2008 and 2011 with no signs of change in it's condition. |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | Low temp steel (50 ksi) |
| Below water: | 50 MV steel (50 ksi) |
| Steel corrosion allowance: | A-36 Steel corrosion wrap through tidal zone: 40' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | Summer 2008 & Summer 2011 (Combined), Global Diving and Salvage carried out a scheduled Level 2 and Level 3 inspection. |

| PLATFORM BAKER | |
|--|--|
| Field Name: | Middle Ground Shoal Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Amoco |
| Structural Design firm: | Earl & Wright/McDermott |
| Fabrication yard (structure): | Kaiser Steel in Oakland, California |
| Installation year and contractor: | 1965; McDermott |
| Water depth (at MLLW): | 102 feet |
| Number and diameter of legs: | Four legs; 14 feet diameter; one well protector leg |
| Number, size and penetration of piling: | Each leg has seven piles in an outer ring and one pile in the center |
| Number, size and penetration of inner piling: | None |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | 136 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 8 wells Leg 2: 8 wells Leg 3: 0 wells Leg 4: 8 wells Leg 5: 1 well |
| Top girders storage tank liquid & capacity: | Produced Water (B-T-0380): 112,728 gal Crude Oil (B-T-0381, B-T-0382): 112,728 gal Produced Water (B-T-0383): 27,720 gal Power Oil (B-T-0384): 27,720 gal Diesel (B-T-0385): 112,728 gal |
| Design criteria | |
| Ice thickness and strength: | Front legs 120 kips/ft. of diameter, back legs 50 kips/ft. |
| Wave height and period: | 30 feet with 9 second period |
| Wind: | 80 mph above elevation 25 feet |
| Earthquake: | 0.1 seismic ground motion |
| Current: | 3900 kips per leg impact load, seismic, ice and current loads applied simultaneously |
| Other Considerations: | Shadow effect |

| | |
|---|---|
| Unusual circumstances during installation: | None |
| Significant modification or damage to topsides: | Minor module additions (quarters extension and Sea King crane). Damaged structural members and structural member removal requiring engineering evaluation of structural integrity. Light, moderate and extreme local and general corrosion. Last inspected: 9/12 |
| Significant structural damage incidents: | Tank explosion in 1968/1969 |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore Associates |
| Type of steel used | |
| Above water: | A-537 Sheffield Low Temp |
| Below water: | 50 MV Steel (50 ksi) |
| Steel corrosion allowance: | A-36 Steel corrosion wrap. 44' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | April, June and July of 2008, Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM BRUCE | |
|--|---|
| Field Name: | Granite Point Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Amoco |
| Structural Design firm: | Earl & Wright/McDermott |
| Fabrication yard (structure): | Kaiser Steel in Oakland, California |
| Installation year and contractor: | 1966; McDermott |
| Water depth (at MLLW): | 62 feet |
| Number and diameter of legs: | Four legs; 14 feet diameter |
| Number, size and penetration of piling: | Eight piles per leg; 30 inch diameter; 65 feet penetration |
| Number, size and penetration of inner piling: | None |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | 122 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 7 wells Leg 2: 1 well Leg 3: 7 wells Leg 4: 6 wells |
| Top girders storage tank liquid & capacity: | Crude Oil (U-T-0180, U-T-0190): 105,000 gal Produced Water (U-T-0240, U-T-0250): 26,250 gal Power Oil (U-T-0320): 184,800 gal Diesel Storage (U-T-0890): 105,000 gal |
| Design criteria | |
| Ice thickness and strength: | Front legs 120 k/ft. of diameter, back legs 50 k/ft. |
| Wave height and period: | 30 feet with 9 second period |
| Wind: | 80 mph above elevation 25 feet |
| Earthquake: | 0.1 g seismic ground motion |
| Current: | 3900 kips per leg impact load, seismic, ice and current load applied simultaneously |
| Other Considerations: | Shadow effect |
| Unusual circumstances during installation: | None |

| | |
|---|---|
| Significant modification or damage to topsides: | Minor module additions. Damaged structural members and removal of structural members, requiring engineering evaluation of structural integrity. Light to extreme local and general corrosion. Last inspected: 9/12 |
| Significant structural damage incidents: | See above |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-537 Sheffield |
| Below water: | A-50 |
| Steel corrosion allowance: | A-36 Steel corrosion wrap. 40' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | July 2009, Global Offshore Divers carried out a scheduled Level 2 and 3 inspection. |

| PLATFORM DILLON | |
|--|---|
| Field Name: | Middle Ground Shoal Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Amoco |
| Structural Design firm: | Earl & Wright/McDermott |
| Fabrication yard (structure): | Kaiser Steel in Oakland, California |
| Installation year and contractor: | 1966; McDermott |
| Water depth (at MLLW): | 92 feet |
| Number and diameter of legs: | Four legs; 14 feet diameter |
| Number, size and penetration of piling: | Eight piles per leg; 30 inch diameter; 88 feet penetration |
| Number, size and penetration of inner piling: | None |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | 152 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 5 wells Leg 2: 7 wells Leg 3: 0 well Leg 4: 5 wells |
| Top girders storage tank liquid & capacity: | Diesel Storage (D-T-0140): 105,000 gal Power Oil (D-T-0160): 184,800 gal Crude Oil (D-T-0240, D-T-0250): 105,000 gal Produced Water (D-T-0600, D-T-0620): 25,200 gal |
| Design criteria | |
| Ice thickness and strength: | Front legs 120 kips/ft. of diameter, back legs 50 kips/ft. |
| Wave height and period: | 30 feet with 9 second period |
| Wind: | 80 mph above elevation 25 feet |
| Earthquake: | 0.1 seismic ground motion |
| Current: | 3900 kips per leg impact load, seismic, ice and current loads applied simultaneously |
| Other Considerations: | Shadow effect |
| Unusual circumstances during installation: | None |

| | |
|---|---|
| Significant modification or damage to topsides: | Minor module additions. Damaged structural members and removal of structural members, requiring engineering evaluation of structural integrity. Light to extreme general and localized corrosion. Loose bolts/studs, missing sections of grating. Last inspected: 9/12 |
| Significant structural damage incidents: | See above |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | 50 MV Steel (50 ksi) |
| Below water: | 50 MV Steel (50 ksi) |
| Steel corrosion allowance: | A-36 Steel corrosion wrap. 40' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | May 2006, Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM DOLLY VARDEN | |
|--|---|
| Field Name: | McArthur River Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Marathon |
| Structural Design firm: | McDermott |
| Fabrication yard (structure): | American Pipe & Construction, Vancouver, Washington |
| Installation year and contractor: | 1967; McDermott |
| Water depth (at MLLW): | 112 feet |
| Number and diameter of legs: | Four; 17 feet diameter |
| Number, size and penetration of piling: | Twelve per leg; 34.5 inch diameter; 180 feet penetration |
| Number, size and penetration of inner piling: | None |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | Bottom to top in annulus. Bottom to minus 12 feet inside inner sleeve. |
| Design codes used (UBC, AISC, API RP 2A, etc.) | AISC, UBC |
| Number of completed wells in each leg: | Leg A-1: 12 wells Leg B-1: 12 wells Leg B-2: 0 wells Leg A-2: 12 wells |
| Top girders storage tank liquid & capacity: | Waste Oil (V-T-0001): 18,480 gal Waste Water (V-T-0002, V-T-0004): 24,780 gal Diesel Storage (V-T-0005): 49,980 gal |
| Design criteria | |
| Ice thickness and strength: | 6 ft. on two front legs, 3 ft. on two back legs; 300 psi |
| Wave height and period: | 28 feet, 8.5 second period |
| Wind: | 60 mph with 80 mph gusts |
| Earthquake: | 0.1 g per 1967 UBC |
| Temperature: | Minus 40° F above water, plus 20° F below water |
| Current: | 10 feet per second |
| Other Considerations: | Twenty year design life |
| Unusual circumstances during installation: | None |

| | |
|---|--|
| Significant modification or damage to topsides: | Minor module additions. Non-typical configurations of beam flanges, damage to structural members and metal deformation on production deck, all requiring engineering evaluation of structural integrity. Light to extreme corrosion (general and local). Last inspected: 4/12 & 5/12 |
| Significant structural damage incidents: | See above |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-537 |
| Below water: | A-36 Steel |
| Steel corrosion allowance: | 1/2 inch through tidal zone. 40' x 1/2" + ice breaker |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | September and October 2011, Global Diving and Salvage carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM GRANITE POINT | |
|--|---|
| Field Name: | Granite Point Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Mobil |
| Structural Design firm: | Brown & Root |
| Fabrication yard (structure): | Kaiser Steel, Oakland, California |
| Installation year and contractor: | 1966; Brown & Root |
| Water depth (at MLLW): | 75 feet |
| Number and diameter of legs: | Four legs; 17 feet diameter |
| Number, size and penetration of piling: | Twelve piles per leg; 33 inch diameter; driven to 40 feet |
| Number, size and penetration of inner piling: | Twelve piles per leg; 26 inch diameter; driven to 105 feet |
| Method of installation (driven, drilled, combination): | Driven |
| Length of grouted interval in legs: | 137 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 8 wells Leg 2: 0 wells Leg 3: 11 wells Leg 4: 2 wells |
| Top girders storage tank liquid & capacity: | Crude Oil (P-T-0180): 21,000 gal Diesel Based Mud (P-T-0480): 119,700 gal Seawater (P-T-0780) Potable Water (P-T-0890B): 24,612 gal Produced Water (P-T-3050): 57,750 gal Diesel Storage (P-T-3210): 118,860 gal |
| Design criteria | |
| Ice thickness and strength: | 5 feet thickness; 43.2 kips/ft. |
| Wave height and period: | 28 feet |
| Temperature: | Minus 38° F to plus 70° F |
| Current: | Current speed 8 knots |
| Other Considerations: | |
| Unusual circumstances during installation: | Platform adrift prior to setting down |

| | |
|---|--|
| Significant modification or damage to topsides: | Module additions and replacement of living quarters (Unocal). Added waterflood (expansion of waterhandling capacity). Damaged structural members and removal of structural members, requiring engineering evaluation of structural integrity. Light to extreme general and local corrosion. Last inspected: 6/12 |
| Significant structural damage incidents: | Jan 15 2009, OSV Monarch struck South two legs of the platform, causing damage to the leg 4 ice-breaker and out of service pump house, as well as the subsea pile guide on the south side of Leg 1 |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-537 |
| Below water: | A-36 |
| Steel corrosion allowance: | 1/2 inch corrosion wrap through the tidal zone. 40' x 1/2" + ice breaker |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | May 2009, Global Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM GRAYLING | |
|--|---|
| Field Name: | McArthur River Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Unocal |
| Structural Design firm: | Brown & Root |
| Fabrication yard (structure): | American Pipe & Construction, Vancouver, Washington |
| Installation year and contractor: | 1967; Brown & Root |
| Water depth (at MLLW): | 125 feet |
| Number and diameter of legs: | Four legs; 17 feet diameter |
| Number, size and penetration of piling: | Twelve piles per leg; 33 inch diameter; driven to 70 feet |
| Number, size and penetration of inner piling: | Twelve piles per leg; 26 inch diameter; driven to 130 feet. Leg 1 has 20 inch inner piles to 190 feet. |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | 192 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 1 well Leg 2: 12 wells Leg 3: 12 wells Leg 4: 12 wells |
| Top girders storage tank liquid & capacity: | Potable Water Crude Oil (G-T-0380A, G-T-0380B): 21,000 gal Waste Water (G-T-0720) Waste Oil (G-T-0760) Diesel Storage (G-T-3090): 106,974 gal |
| Design criteria | |
| Ice thickness and strength: | Front legs 260 kips/ft. of diameter, back legs 160 kips/ft. |
| Wave height and period: | 28 feet with 8.5 second period |
| Wind: | 100 mph |
| Earthquake: | 0.1 g seismic ground motion |
| Temperature: | Minus 15° F to plus 70° F |
| Current: | |
| Other Considerations: | |

| | |
|---|--|
| Unusual circumstances during installation: | Yes, tower leak required to repair |
| Significant modification or damage to topsides: | Minor module additions. Damaged structural members and structural member removal, requiring engineering evaluation of structural integrity. Light to extreme general and local corrosion issues. Last inspected: 5/12 |
| Significant structural damage incidents: | See above |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-537 |
| Below water: | A-36 |
| Steel corrosion allowance: | 1/2 inch corrosion wrap through tidal zone. 40' x 1/2" + ice breakers |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | July and August 2008, Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM KING SALMON | |
|--|--|
| Field Name: | McArthur River Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Arco |
| Structural Design firm: | Earl & Wright |
| Fabrication yard (structure): | Kaiser Steel in Oakland, California |
| Installation year and contractor: | 1967; McDermott |
| Water depth (at MLLW): | 73 feet |
| Number and diameter of legs: | Four legs; 15.5 feet |
| Number, size and penetration of piling: | Eight piles per leg; 36 inch diameter; 100 feet penetration; 33 inch sleeves near mudline |
| Number, size and penetration of inner piling: | Eight per leg; 24 inch diameter; 260 feet penetration |
| Method of installation (driven, drilled, combination): | Combination |
| Length of grouted interval in legs: | 128 feet |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| Number of completed wells in each leg: | Leg 1: 8 wells Leg 2: 8 wells Leg 3: 0 wells Leg 4: 8 wells |
| Top girders storage tank liquid & capacity: | Produced Water (L-T-0160): 16,800 gal Crude Oil (L-T-0170): 29,400 gal Crude Oil (L-T-0180, L-T-0180A, L-T-0180B): 31,248 gal Waste Oil (L-T-0190): 15,540 gal Diesel (L-T-1750): 99,960 gal Diesel (L-T-1830): 3,192 gal Potable Water (L-T-2010, L-T-2020): 21,000 gal |
| Design criteria | |
| Ice thickness and strength: | 42 inch; 300 psi |
| Wave height and period: | 28 feet with 8.5 second period |
| Wind: | 65 mph with 100 mph gusts |
| Earthquake: | 0.06 g per UBC 1964 |
| Temperature: | Minus 40° F above water, plus 28° F below water |
| Current: | 12 feet per second |

| | |
|---|--|
| Other Considerations: | 20 year design life |
| Unusual circumstances during installation: | None |
| Significant modification or damage to topsides: | Minor module additions. Damaged structural members, non-typical configuration and missing joints, and deflections in the plate girders, all requiring engineering evaluation of structural integrity. Light to extreme general and localized corrosion. Last inspected: 11/12 |
| Significant structural damage incidents: | See above |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-537 Grade A (above Elev -25) |
| Below water: | A-537 Grade B (below Elev -25) |
| Steel corrosion allowance: | 0.7" of extra wall thickness in the tidal zone. 40' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | July, October and November 2007, Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM MONOPOD | |
|--|---|
| Field Name: | Trading Bay Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Unocal |
| Structural Design firm: | Brown & Root |
| Fabrication yard (structure): | American Pipe & Construction, Vancouver, Washington |
| Installation year and contractor: | 1966; Brown & Root |
| Water depth (at MLLW): | 66 feet |
| Number and diameter of legs: | One leg, 28.5 feet in diameter |
| Number, size and penetration of piling: | 32 piles; 36 inch diameter with 101 feet penetration |
| Number, size and penetration of inner piling: | 32 conductor piles; 20 inch diameter with 97 feet penetration |
| Method of installation (driven, drilled, combination): | Driven |
| Length of grouted interval in legs: | Center leg has 33 feet of grout |
| Design codes used (UBC, AISC, API RP 2A, etc.) | UBC, AISC |
| | |
| Number of completed wells in each leg: | 31 wells |
| Top girders storage tank liquid & capacity: | Potable Water (M-T-NA): 19,698 gal Drilling Mud (M-T-1000): 16,296 gal Diesel Storage (M-T-3000): 100,548 gal |
| | |
| Design criteria | |
| Ice thickness and strength: | Six feet; 300 psi (7300 kips) |
| Wave height and period: | 28 feet with 8.5 second period |
| Wind: | 100 mph |
| Earthquake: | 0.1 g seismic ground motion |
| Current: | 10 ft./sec |
| Other Considerations: | Single caisson |
| | |
| Unusual circumstances during installation: | None |

| | |
|---|---|
| Significant modification or damage to topsides: | Minor module additions. Addition of waterflood system. Damaged or removed structural members, non-typical configuration in Bingham room, incomplete welding, and extreme general and local corrosion on walkway leading to flare tip, all requiring engineering evaluation. Light to extreme general and local corrosion elsewhere. Last inspected: 10/12 |
| Significant structural damage incidents: | South horizontal separated from the West pontoon at the SW weld. SE weld had heavy knife-corrosion but no crack (2011). NW weld had open crack (water flowing in and out, 2011). |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-537 |
| Below water: | A-36 |
| Steel corrosion allowance: | 1/2 inch wear plate through tidal zone. 35' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | September and October 2010, Global Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |

| PLATFORM STEELHEAD | |
|--|--|
| Field Name: | McArthur River Field |
| Platform Operator: | Hilcorp |
| Platform Owner(s): | Hilcorp |
| Original operator: | Marathon |
| Structural Design firm: | McDermott |
| Fabrication yard (structure): | NKK, Japan |
| Installation year and contractor: | 1986; Brown & Root |
| Water depth (at MLLW): | 183 feet |
| Number and diameter of legs: | Four; 18 feet diameter |
| Number, size and penetration of piling: | Twelve per leg; 34 inch diameter; 135 feet penetration |
| Number, size and penetration of inner piling: | Ten 26 inch drilled inner piling installed to 650 feet in Leg B1 following blowout |
| Method of installation (driven, drilled, combination): | 24 driven, 24 combination with drilled pilot hole |
| Length of grouted interval in legs: | Annulus grouted from bottom to top of leg |
| Design codes used (UBC, AISC, API RP 2A, etc.) | API RP 2A |
| Number of completed wells in each leg: | Leg A-1: 10 wells Leg A-2: 0 wells Leg B-1: 8 wells Leg B-2: 10 wells |
| Top girders storage tank liquid & capacity: | Diesel Storage (H-T-0032A): 71,400 gal Diesel Storage (H-T-0032B): 35,700 gal Diesel Storage (H-T-0032C): 42,480 gal Waste Water (H-T-0037): 42,000 gal |
| Design criteria | |
| Ice thickness and strength: | 50 inch thick; 300 psi |
| Wave height and period: | 28 feet with 8.5 second period |
| Wind: | 80 mph with 107 mph gusts |
| Earthquake: | Site specific, Ertec, C.B. Krause |
| Temperature: | Minus 20° F above water, plus 28.6° F below water |
| Current: | 12.65 feet per second |
| Other Considerations: | Twenty year design life |
| Unusual circumstances during installation: | None |

| | |
|---|---|
| Significant modification or damage to topsides: | Minor module additions. Damaged or removed/missing structural members, damaged insulation and non-typical configuration on deck beams, requiring engineering evaluation of structural integrity and replacement potential. Light to extreme general and local corrosion. Last inspected: 11/12 |
| Significant structural damage incidents: | See above |
| Platform structural design reassessment company & year: | 2001 - Hopper Elmore and Associates |
| Type of steel used | |
| Above water: | A-633 Gr. C |
| Below water: | A-633 Gr. C |
| Steel corrosion allowance: | 40' x 1/2" |
| Type of cathodic protection: | Impressed current cathodic protection system |
| Dates and API RP 2A levels of underwater inspection: | September and October of 2008, Offshore Divers carried out a scheduled API Level 2 and 3 inspection. |